## \*\* LABORATORY ANALYSIS REPORT \*\*

Radon test result report for: ADEL SCHOOL HALL

| Kit #   | Room Id   | Started               | Ended                | pCi/L         | Analyzed   |
|---------|-----------|-----------------------|----------------------|---------------|------------|
| 7301333 | EAST ROOM | 2020-11-27 @ 11:00 am | 2020-11-29 @ 2:00 pm | $1.7 \pm 0.8$ | 2020-12-07 |
| 7301334 | WEST ROOM | 2020-11-27 @ 11:00 am | 2020-11-29 @ 2:00 pm | $1.2 \pm 0.8$ | 2020-12-07 |
|         |           |                       | •                    |               |            |

## \*\* LABORATORY ANALYSIS REPORT \*\*

Radon test result report for: ADEL SCHOOL MAIN

| Kit#    | Room Id        | Started          | Ended                       | pCi/L         | Analyzed   |
|---------|----------------|------------------|-----------------------------|---------------|------------|
| 7301329 | EAST CLASSROOM | 2020-11-27 @ 11: | :00 am 2020-11-29 @ 2:00 pm | $1.2 \pm 0.7$ | 2020-12-07 |
| 7301331 | HALLWAY        | 2020-11-27 @ 11: | :00 am 2020-11-29 @ 2:00 pm | $1.0 \pm 0.8$ | 2020-12-07 |
| 7301332 | LIBRARY        | 2020-11-27 @ 11: | :00 am 2020-11-29 @ 2:00 pm | < 0.3         | 2020-12-07 |
| 7301330 | WEST CLASSROOM | 2020-11-27 @ 11: | :00 am 2020-11-29 @ 2:00 pm | $1.1 \pm 0.8$ | 2020-12-07 |
|         |                |                  |                             |               |            |

## \*\* LABORATORY ANALYSIS REPORT \*\*

Radon test result report for: ADEL SCHOOL PRESCHOOL

| Kit#    | Room Id   | Started               | Ended                | pCi/L | Analyzed   |
|---------|-----------|-----------------------|----------------------|-------|------------|
| 7301335 | CLASSROOM | 2020-11-27 @ 11:00 am | 2020-11-29 @ 2:00 pm | < 0.3 | 2020-12-07 |
| 7301336 | S EAST    | 2020-11-27 @ 11:00 am | 2020-11-29 @ 2:00 pm | < 0.3 | 2020-12-07 |
|         |           |                       | Ť                    |       |            |

## \*\* LABORATORY ANALYSIS REPORT \*\*

Radon test result report for: ADEL SCHOOL TEACHERAGE

| Kit#    | Room Id     | Started               | Ended                | pCi/L         | Analyzed   |
|---------|-------------|-----------------------|----------------------|---------------|------------|
| 7301337 | LIVING ROOM | 2020-11-27 @ 11:00 am | 2020-11-29 @ 2:00 pm | $2.0 \pm 0.8$ | 2020-12-07 |
|         |             |                       | •                    |               |            |

## \*\* LABORATORY ANALYSIS REPORT \*\*

### Radon test result report for: PLUSH SCHOOL MAIN

| Kit#    | Room Id       | Started              | Ended                | pCi/L         | Analyzed   |
|---------|---------------|----------------------|----------------------|---------------|------------|
| 7301326 | CLASSROOM     | 2020-11-27 @ 1:00 pm | 2020-11-29 @ 2:00 pm | $0.9 \pm 0.7$ | 2020-12-07 |
| 7301327 | COMPUTER ROOM | 2020-11-27 @ 1:00 pm | 2020-11-29 @ 2:00 pm | $1.8 \pm 0.8$ | 2020-12-07 |
| 7301338 | HALLWAY       | 2020-11-27 @ 1:00 pm | 2020-11-29 @ 2:00 pm | < 0.3         | 2020-12-07 |
|         |               |                      |                      |               |            |

# \*\* LABORATORY ANALYSIS REPORT \*\*

Radon test result report for:
PLUSH SCHOOL TEACHERAGE
TEACHERAGE

| Kit#    | Room Id     | Started              | Ended                | pCi/L         | Analyzed   |
|---------|-------------|----------------------|----------------------|---------------|------------|
| 7301328 | LIVING ROOM | 2020-11-27 @ 1:00 pm | 2020-11-29 @ 2:00 pm | $2.0 \pm 0.8$ | 2020-12-07 |
|         |             | •                    | •                    |               |            |